
## THINK TECHSMART, FIRST

## TechSmart® HID Headlight Ballast



**The Problem:** Despite their superiority to halogen headlights, HID Headlights can still fail, typically from overheating, moisture intrusion, damage from a frontal collision, or burning out from repeated duty cycles. If one of those scenarios occurs, it can cause the system to become inoperative, creating reduced visibility and safety concerns for drivers and motorists.

**Our Response:** To help restore proper lighting function to HID light systems, TechSmart® created OE-Exact Match HID Headlight Ballasts. That means they are direct-replacement parts that match the fit, form, and function of the originals. Plus, as DOT-certified parts, our HID Headlight Ballasts comply with Federal Motor Vehicle Safety Standards.



We believe premium quality should extend to aftermarket parts. That's why we created our OE-Exact Match HID Headlight Ballasts. Exceptional quality without sacrificing fit, form, and function.

