

GM Tail Light Wiring Harnesses

Standard's all-new complete harness assemblies eliminate the need to cut and splice the original harness when a single socket fails. These components are precision engineered and come completely assembled to make replacement quick, easy and reliable.



GMC Sierra 1500, 2500, 3500
(2015-14) VIO: 550K



S2619
Left Rear



S2620
Right Rear



Chevrolet Silverado 1500, 2500, 3500
(2015-14) VIO: 1.3M



S2621
Left Rear



S2622
Right Rear



GMC Sierra / Chevrolet Silverado
1500, 2500, 3500
(2019-16) VIO: 2.4M



S2623
Left Rear



S2624
Right Rear



For more specific application data, visit StandardBrand.com