

Ignition Coils. *When OE Fails...Trust Standard®*



UF874
Subaru Cars & SUVs
(2022-19) 2.5L
VIO: 1M



UF893
Ford Super Duty
(2022-20) VIO: 7.3L
VIO: 226K



UF882
Mazda Cars & SUVs
(2021-18) 2.5L
VIO: 801K



UF916
Lexus Cars & SUVs
(2020-15) 2.0L
VIO: 317K



UF917
Porsche Cars & SUVs
(2021-17) 2.0, 2.9, 3.0, 4.0L
VIO: 206K



UF896
Volkswagen Cars & SUVs
(2022-21) 1.4, 2.0, 3.6L
VIO: 455K



UF889
Hyundai Cars & SUVs
(2022-20) 1.6 / 2.0L
VIO: 484K



UF873
Subaru Cars & SUVs
(2022-19) 2.4L
VIO: 326K



UF890
Hyundai Sonata
(2022-20) 2.5L
VIO: 520K



For more specific application data, visit StandardBrand.com



UP AND COMING

These Coils and Coil Kits have been released in the past few years and are increasing in popularity



UF865

Ford Super Duty
(2021-18) 6.2L
VIO: 405K



UF596K4

Toyota Cars & SUVs
(2019-08) 1.8 / 2.0L
VIO: 4.6M



UF349K6

Nissan / Infiniti Cars,
Trucks & SUVs (2020-02) 3.5 / 4.0L
VIO: 2.4M



UF869

Ford F-150 / Mustang
(2021-18) 5.0L
VIO: 783K



UF487K6

Lexus / Toyota Cars, Trucks & SUVs
(2019-05) 3.0 / 3.5 / 4.0L
VIO: 7.8M



UF667K6

BMW Cars & SUVs
(2019-99) 2.5 / 3.0 / 3.2L
VIO: 2.1M

